

Roads	Water and sanitary sewer mains	Power Lines and Poles	Sewage Lagoons	Solid Waste Sites	Parks

	Municipal Boundary		Community
	Hay River Reserve		Park / Recreation Area
	Hay River Dene Reserve		Arena
	Cemetery		Campground
	Religious Building		Picnic Site
	Ritual Cultural Area		Swimming Pool
	Pits, Borrow Sites, Quarries, Dump Sites		Marine Transport
	Tank		Medical Centre
	Transmission Line		Municipal Hall
	Coast Guard Station		Museum
	Communication Tower		Office
	Community Centre		Penal Building
	Educational Building		Police Station
	Fire Station		Public Dock
	Fuel Facility		Senior Citizens Home
	Garage		Water Pump House
	Hospital		Water Truckfill Station
	Library		Water Treatment Plant
	Expressway / Highway		Railway
	Collector		Bridge
	Other street or road		Culvert
	Trail		Airport
	Waterbody		Railway Station
	Lagoon / Reservoir / Dugout		Seaplane Base
	Permanent Watercourse		Floodway
	Intermittent Watercourse		Floodway Fringe
	Ditch		Historical Fire 1969
	No Identified Risk		Precipitation Increase
	Flooding and Coastal Erosion		Wildfire
	Permafrost Degradation		Wind Increase
	No Identified Risk		Moderate-low
	Low		Moderate-high
			High


Government of Northwest Territories  
**Assessment of Climate Change Impacts on Infrastructure in all NWT communities using the PIEVC protocol**  
 Northwest Territories, Canada

**Map 7**  
**Hay River and Kát'odeeche Risk Profile**

**Sources :**  
 CanVec, 1/50 000, NRCan, 2019-12-20  
 BNDT, 1/50 000, NRCan, 2016-04-22  
 CanVec, 1/1 000 000, NRCan, 2019-12-20  
 CanVec, 1/15 000 000, NRCan, 2019-12-20  
 Administration of the Territorial Land Acts System (ATLAS), Government of Northwest Territories, 2019  
 CNES and Airbus, from Google Earth Pro, 2019-06-09

0 350 700 m  
 NAD83, UTM ZONE 11N  
 2020-06-12

Preparation : Y. Chavallaz  
 Drawing : V. Venne  
 Verification : J.-P. Martin  
 191\_14133\_PIEVC\_M7\_003\_HayKat'\_wspm\_200612.mxd



Boundaries and measurements shown on this document must not be used for engineering or land survey delineation. A land register analysis conducted by a land surveyor was not undertaken.