




● Community	🚒 Fire Station
<b>Infrastructures</b>	🛢️ Fuel Facility
📏 Pits, Borrow Sites, Quarries, Dump Sites	🏛️ Municipal Hall
🎓 Educational Building	🏭 Water Treatment Plant
<b>Transport</b>	✈️ Airport
— Other street or road	
- - - Trail	
<b>Hydrography</b>	— Permanent Watercourse
🌊 Waterbody	- - - Ditch
🟦 Lagoon / Reservoir / Dugout	
<b>Risk Type</b>	📏 Precipitation Increase
○ No Identified Risk	🔥 Wildfire
⬡ Flooding and Coastal Erosion	⬡ Wind Increase
⬡ Permafrost Degradation	
<b>Risk Level</b>	🟡 Moderate-low
🟡 No Identified Risk	🟠 Moderate-high
🟢 Low	🔴 High




 Government of Northwest Territories  
**Assessment of Climate Change Impacts on Infrastructure in all NWT communities using the PIEVC protocol**  
 Northwest Territories, Canada

**Map 19**  
**Jean Marie River Risk Profile**

**Sources :**  
 CanVec, 1/50 000, NRCan, 2019-12-20  
 BNDT, 1/50 000, NRCan, 2016-04-22  
 CanVec, 1/1 000 000, NRCan, 2019-12-20  
 CanVec, 1/15 000 000, NRCan, 2019-12-20  
 Administration of the Territorial Land Acts System (ATLAS), Government of Northwest Territories, 2019  
 Digital Globe, from Google Earth Pro, 2015-05-27

0 80 160 m  
 NAD83, UTM ZONE 10N

2020-06-12  
 Preparation : Y. Chavallaz  
 Drawing : V. Venne  
 Verification : J.-P. Martin  
 191\_14133\_PIEVC\_M19\_019\_JMRiver\_wspm\_200612.mxd



Boundaries and measurements shown on this document must not be used for engineering or land survey delineation. A land register analysis conducted by a land surveyor was not undertaken.